





Attention : Patrick Wren

004876

CLIENT NAME: Recovery Manager		DEBTOR NAME Customer, Joe		VEHICLE IDENTIFICATION #: 4A3AK34T17E004876		CASE #: 03-12002	
DATE RECOVERED: 5/4/2005		YEAR, MAKE, & MODEL: 2007 Mitsubishi Eclipse				ACCOUNT #: 123456789	
POLICE PRECINCT REPORTED (INCLUDE PHONE#) Daytona Beach Police Department					Repo Time : _____ Log Time : _____		TAG NUMBER FXV54Y
PREPARED BY (PRINT COMPANY NAME): Recovery Manager		DATE PREPARED: 5/4/2005	IS UNIT RIDEABLE: <input checked="" type="radio"/> YES <input type="radio"/> NO (IF NOT EXPLAIN IN REMARKS BELOW)				
HOURS/MILEAGE 77777777	TRAILER <input type="radio"/> YES <input type="radio"/> NO	IGNITION KEY: <input type="radio"/> YES <input checked="" type="radio"/> NO		COLOR: WHITE	GENERAL CONDITION: <input checked="" type="radio"/> GOOD <input type="radio"/> AVERAGE <input type="radio"/> POOR <input type="radio"/> JUNK		
ACCESSORIES							
<input checked="" type="checkbox"/> SPEEDOMETER	<input checked="" type="checkbox"/> TACHOMETER	<input checked="" type="checkbox"/> FWD CONTROLS	<input type="checkbox"/> CRUISE CONTROL				
<input checked="" type="checkbox"/> DISK BRAKES	<input type="checkbox"/> AUTOMATIC	<input checked="" type="checkbox"/> CUSTOM WHEELS	<input checked="" type="checkbox"/> TOOL BOX	<input checked="" type="checkbox"/> OTHER			
MECHANICAL <input checked="" type="radio"/> GOOD <input type="radio"/> AVERAGE <input type="radio"/> POOR	TRAILER INFORMATION (IF ANY) YEAR/MAKE/MODEL: _____ VIN#: _____			TIRES G - GOOD A - AVERAGE B - BALD N - NONE LEFT FRONT G RIGHT FRONT A LEFT REAR A RIGHT REAR A SPARE B			
LIST ADDITIONAL PROBLEMS AND / OR EXPLANATIONS IN THE COMMENT SECTION BELOW							
BODY: G - GOOD A - AVERAGE P - POOR D - DENTED R - RUST				ARE DENTS FROM COLLISION DAMAGE?			
OVERALL CONDITION: BODY <u>A</u> PAINT <u>A</u> BUMPER <u>A</u>				<input checked="" type="radio"/> YES <input type="radio"/> NO			
PLACE A "C" (CRACKED) OR "B" (BROKEN), IF APPROPRIATE, ON THE PROPER LOCATIONS OF THE UNITS PICTURED BELOW:							
							
REMARKS / MISSING EQUIPMENT:							
VEHICLES RECOVERED FROM: <input type="radio"/> CUSTOMER <input checked="" type="radio"/> OTHER (SPECIFY) _____				ADDRESS RECOVERED FROM: 463 N Yonge St, Ormond Beach, FL 32174			
WAS RELEASE SIGNED BY CUSTOMER? <input checked="" type="radio"/> YES <input type="radio"/> NO				IF NO, EXPLAIN Involuntary Repossession			
PERSONAL PROPERTY <input checked="" type="radio"/> YES <input type="radio"/> NO				HAVE THE AUCTION SIGN BELOW INDICATING KEYS WERE RECEIVED WHEN THE VEHICLE WAS TURNED OVER TO THEM. _____ AUCTION SIGNATURE PRINT NAME			
ADDRESS WHERE CAR IS BEING STORED (REQUIRED): 1514 Granada Ave, Holly Hill, FL 32174				COMPLETED BY: Repossessed - Pending			