

Attention : Patrick Wren

004876

CLIENT NAME: <b>Recovery Manager</b>		DEBTOR NAME <b>Customer, Joe</b>		VEHICLE IDENTIFICATION #: <b>4A3AK34T17E004876</b>		CASE #: <b>03-12002</b>	
DATE RECOVERED: <b>5/4/2005</b>		YEAR, MAKE, & MODEL: <b>2007 Mitsubishi Eclipse</b>				ACCOUNT #: <b>123456789</b>	
POLICE PRECINCT REPORTED (INCLUDE PHONE#): Repo Time : <b>Daytona Beach Police Department</b> Log Time :						TAG NUMBER TAG EXPIRATION <b>FXV54Y</b>	
PREPARED BY (PRINT COMPANY NAME): <b>Recovery Manager</b>		DATE PREPARED <b>5/4/2005</b>		IS UNIT DRIVEABLE: <input checked="" type="radio"/> YES <input type="radio"/> NO (IF NOT EXPLAIN IN REMARKS BELOW)			
MILEAGE <b>77777777</b>		IGNITION KEY: <input type="radio"/> YES <input checked="" type="radio"/> NO		COLOR: <b>White</b>		GENERAL CONDITION: <input checked="" type="radio"/> GOOD <input type="radio"/> AVERAGE <input type="radio"/> POOR <input type="radio"/> JUNK	
<input type="radio"/> 5 DIGIT <input checked="" type="radio"/> 6 DIGIT		TRUNK KEY: <input checked="" type="radio"/> YES <input type="radio"/> NO					
ACCESSORIES							
<input checked="" type="checkbox"/> MOONROOF / SUNROOF		<input checked="" type="checkbox"/> A/C		<input type="checkbox"/> P. SEATS		<input checked="" type="checkbox"/> FM RADIO	
<input type="checkbox"/> AUTO TRANS		<input checked="" type="checkbox"/> P. WINDOWS		<input checked="" type="checkbox"/> AM/FM/CD		<input type="checkbox"/> CRUISE CONTROL	
				<input checked="" type="checkbox"/> AM/FM/TAPE		<input type="checkbox"/> TILT WHEEL	
						<input checked="" type="checkbox"/> AIRBAGS	
						<input checked="" type="checkbox"/> CUSTOM WHEELS	
MECHANICAL		GLASS		TIRES G - GOOD A - AVERAGE B - BALD N - NONE			
<input checked="" type="radio"/> GOOD		<input checked="" type="radio"/> GOOD <input type="radio"/> SCRATCHED		LEFT FRONT <b>G</b>		RIGHT FRONT <b>A</b>	
<input type="radio"/> AVERAGE		<input type="radio"/> BROKEN (Explain)		LEFT REAR <b>A</b>		RIGHT REAR <b>A</b>	
<input type="radio"/> POOR				SPARE <b>B</b>		INTERIOR: <input type="radio"/> LEATHER <input type="radio"/> CLOTH	
						<input type="radio"/> GOOD <input checked="" type="radio"/> AVERAGE	
						<input type="radio"/> POOR (Explain Below)	
LIST ADDITIONAL PROBLEMS AND / OR EXPLANATIONS IN THE COMMENT SECTION BELOW							
BODY: G - GOOD A - AVERAGE P - POOR D - DENTED R - RUST				ARE DENTS FROM COLLISION DAMAGE?			
OVERALL CONDITION: BODY <u>  A  </u> PAINT <u>  A  </u> BUMPER <u>  A  </u>				<input checked="" type="radio"/> YES <input type="radio"/> NO			
PLACE A "D" (DENTED) OR "R" (RUSTED) OR "S" (SCRATCHED) IF APPROPRIATE, ON THE PROPER LOCATIONS OF THE VEHICLES PICTURED BELOW:							
Drivetrain: <input type="radio"/> 2WD <input type="radio"/> 4WD <input type="radio"/> AWD							
Engine Size: <input type="radio"/> 4 <input type="radio"/> 6 <input type="radio"/> 8 <input type="radio"/> 10 <input type="radio"/> Diesel							
REMARKS / MISSING EQUIPMENT:							
VEHICLES RECOVERED FROM: <input type="radio"/> CUSTOMER <input checked="" type="radio"/> OTHER (SPECIFY) _____				ADDRESS RECOVERED FROM: <b>463 N Yonge St, Ormond Beach, FL 32174</b>			
WAS RELEASE SIGNED BY CUSTOMER? <input checked="" type="radio"/> YES <input type="radio"/> NO				IF NO, EXPLAIN <b>Involuntary Repossession</b>			
PERSONAL PROPERTY <input checked="" type="radio"/> YES <input type="radio"/> NO				HAVE THE AUCTION SIGN BELOW INDICATING KEYS WERE RECEIVED WHEN THE VEHICLE WAS TURNED OVER TO THEM.			
				_____ AUCTION SIGNATURE		_____ PRINT NAME	
ADDRESS WHERE CAR IS BEING STORED (REQUIRED): <b>1514 Granada Ave, Holly Hill, FL 32174</b>				COMPLETED BY: <b>Repossessed - Pending</b>			