

Attention : Patrick Wren

004876

CLIENT NAME: Recovery Manager	DEBTOR NAME Customer, Joe	VEHICLE IDENTIFICATION #: 4A3AK34T17E004876	CASE #: 03-12002
DATE RECOVERED: 5/4/2005	YEAR, MAKE, & MODEL: 2007 Mitsubishi Eclipse		ACCOUNT #: 123456789

POLICE PRECINCT REPORTED (INCLUDE PHONE# **Daytona Beach Police Department**)

PREPARED BY (PRINT COMPANY NAME): Recovery Manager	DATE PREPARED: 5/4/2005	IS UNIT RIDEABLE: <input checked="" type="radio"/> YES <input type="radio"/> NO	Repo Time	Log Time
--	-----------------------------------	--	-----------	----------

HOURS/MILEAGE 77777777	TRAILER <input type="radio"/> YES <input type="radio"/> NO	IGNITION KEY: <input type="radio"/> YES <input checked="" type="radio"/> NO	COLOR: WHITE	GENERAL CONDITION: <input checked="" type="radio"/> GOOD <input type="radio"/> AVERAGE <input type="radio"/> POOR <input type="radio"/> JUNK
BROKEN GLASS <input checked="" type="radio"/> YES <input type="radio"/> NO				

ACCESSORIES

<input type="checkbox"/> BOAT	<input checked="" type="checkbox"/> SPEEDOMETER	<input checked="" type="checkbox"/> IB/OB MOTOR	<input checked="" type="checkbox"/> TROLLING MTR	<input checked="" type="checkbox"/> WINCH / ANCHOR	<input type="checkbox"/> FISH FINDER
	<input checked="" type="checkbox"/> A/C	<input type="checkbox"/> REFRIGERATOR	<input type="checkbox"/> STOVE	<input checked="" type="checkbox"/> AM/FM/TAPE	<input type="checkbox"/> COVER
TRAILER _ 2 15/16" BALL SIZE	<input type="checkbox"/> WINCH MANUAL	<input checked="" type="checkbox"/> WINCH ELE	<input checked="" type="checkbox"/> CUSTOM WHEELS		


MECHANICAL <input checked="" type="radio"/> GOOD <input type="radio"/> AVERAGE <input type="radio"/> POOR	TRAILER INFORMATION (IF ANY) YEAR/MAKE/MODEL: VIN#:	TIRES G - GOOD A - AVERAGE B - BALD N - NONE LEFT FRONT G RIGHT FRONT A LEFT REAR A RIGHT REAR A
--	---	--

LIST ADDITIONAL PROBLEMS AND / OR EXPLANATIONS IN THE COMMENT SECTION BELOW

BODY: G - GOOD A - AVERAGE P - POOR D - DENTED R - RUST ARE DENTS/CRACKS FROM COLLISION DAMAGE?

OVERALL CONDITION: FIBERGLASS **A** _ PAINT **A** _ TRAILER **A** _ YES NO

PLACE A "C" (CRACKED) OR "B" (BROKEN), IF APPROPRIATE, ON THE PROPER LOCATIONS OF THE UNITS PICTURED BELOW:



Engine Size: 4 6 8 10 Diesel

REMARKS / MISSING EQUIPMENT / ADDITIONAL EQUIPMENT NOT LISTED ABOVE:

BOAT RECOVERED FROM: <input type="radio"/> CUSTOMER <input checked="" type="radio"/> OTHER (SPECIFY) _____	ADDRESS RECOVERED FROM: 463 N Yonge St, Ormond Beach, FL 32174
--	--

WAS RELEASE SIGNED BY CUSTOMER? YES NO IF NO. EXPLAIN

PERSONAL PROPERTY <input checked="" type="radio"/> YES <input type="radio"/> NO	HAVE THE AUCTION SIGN BELOW INDICATING KEYS WERE RECEIVED WHEN THE VEHICLE WAS TURNED OVER TO THEM. _____ AUCTION SIGNATURE PRINT NAME
---	--

ADDRESS WHERE CAR IS BEING STORED (REQUIRED): 1514 Granada Ave, Holly Hill, FL 32174	COMPLETED BY: Repossessed - Pending
--	---