

Attention : Patrick Wren

004876

CLIENT NAME: Recovery Manager		DEBTOR NAME Customer, Joe		VEHICLE IDENTIFICATION #: 4A3AK34T17E004876		CASE #: 03-12002	
DATE RECOVERED: 5/4/2005		YEAR, MAKE, & MODEL: 2007 Mitsubishi Eclipse				ACCOUNT #: 123456789	
POLICE PRECINCT REPORTED (INCLUDE PHONE#): Repo Time : Daytona Beach Police Department						Log Time : _____	
PREPARED BY (PRINT COMPANY NAME): Recovery Manager		DATE PREPARED 5/4/2005		IS UNIT DRIVEABLE: <input checked="" type="radio"/> YES <input type="radio"/> NO (IF NOT EXPLAIN IN REMARKS BELOW)			
MILEAGE 77777777		IGNITION KEY: <input type="radio"/> YES <input checked="" type="radio"/> NO		COLOR: White		GENERAL CONDITION: <input checked="" type="radio"/> GOOD <input type="radio"/> AVERAGE <input type="radio"/> POOR <input type="radio"/> JUNK	
<input type="radio"/> 5 DIGIT <input checked="" type="radio"/> 6 DIGIT		TRUNK KEY: <input checked="" type="radio"/> YES <input type="radio"/> NO					
ACCESSORIES <input checked="" type="checkbox"/> MOONROOF / SUNROOF <input checked="" type="checkbox"/> A/C <input type="checkbox"/> P. SEATS <input checked="" type="checkbox"/> FM RADIO <input type="checkbox"/> CRUISE CONTROL <input checked="" type="checkbox"/> AIRBAGS <input type="checkbox"/> AUTO TRANS <input checked="" type="checkbox"/> P. WINDOWS <input checked="" type="checkbox"/> AM/FM/CD CHANGER <input checked="" type="checkbox"/> AM/FM/TAPE <input type="checkbox"/> TILT WHEEL <input checked="" type="checkbox"/> CUSTOM WHEELS							
MECHANICAL <input checked="" type="radio"/> GOOD <input type="radio"/> AVERAGE <input type="radio"/> POOR		GLASS <input checked="" type="radio"/> GOOD <input type="radio"/> SCRATCHED <input type="radio"/> BROKEN(Explain)		TIRES G - GOOD A - AVERAGE B - BALD N - NONE LEFT FRONT G RIGHT FRONT A LEFT REAR A RIGHT REAR A SPARE B		INTERIOR: <input type="radio"/> LEATHER <input type="radio"/> CLOTH <input type="radio"/> GOOD <input checked="" type="radio"/> AVERAGE <input type="radio"/> POOR (Explain Below)	
LIST ADDITIONAL PROBLEMS AND / OR EXPLANATIONS IN THE COMMENT SECTION BELOW							
BODY: G - GOOD A - AVERAGE P - POOR D - DENTED R - RUST				ARE DENTS FROM COLLISION DAMAGE?			
OVERALL CONDITION: BODY <u>A</u> PAINT <u>A</u> BUMPER <u>A</u>				<input checked="" type="radio"/> YES <input type="radio"/> NO			
PLACE A "D" (DENTED) OR "R" (RUSTED), IF APPROPRIATE, ON THE PROPER LOCATIONS OF THE VEHICLES PICTURED BELOW:							
Drivetrain: <input type="radio"/> 2WD <input type="radio"/> 4WD <input type="radio"/> AWD							
Engine Size: <input type="radio"/> 4 <input type="radio"/> 6 <input type="radio"/> 8 <input type="radio"/> 10 <input type="radio"/> Diesel							
REMARKS / MISSING EQUIPMENT:							
VEHICLES RECOVERED FROM: <input type="radio"/> CUSTOMER <input checked="" type="radio"/> OTHER (SPECIFY) _____				ADDRESS RECOVERED FROM: 463 N Yonge St, Ormond Beach, FL 32174			
WAS RELEASE SIGNED BY CUSTOMER? <input checked="" type="radio"/> YES <input type="radio"/> NO				IF NO, EXPLAIN <i>Involuntary Repossession</i>			
PERSONAL PROPERTY <input checked="" type="radio"/> YES <input type="radio"/> NO				HAVE THE AUCTION SIGN BELOW INDICATING KEYS WERE RECEIVED WHEN THE VEHICLE WAS TURNED OVER TO THEM.			
				_____ AUCTION SIGNATURE		_____ PRINT NAME	
ADDRESS WHERE CAR IS BEING STORED (REQUIRED): 1514 Granada Ave, Holly Hill, FL 32174				COMPLETED BY: Repossessed - Pending			