



Attention : Patrick Wren

004876

CLIENT NAME: <b>Recovery Manager</b>		DEBTOR NAME <b>Customer, Joe</b>		VEHICLE IDENTIFICATION #: <b>4A3AK34T17E004876</b>		CASE #: <b>03-12002</b>	
DATE RECOVERED: <b>5/4/2005</b>		YEAR, MAKE, & MODEL: <b>2007 Mitsubishi Eclipse</b>				ACCOUNT #: <b>123456789</b>	
POLICE PRECINCT REPORTED (INCLUDE PHONE#Repo Time :                      Log Time : <b>Daytona Beach Police Department</b>					TAG NUMBER TAG EXPIRATION <b>FXV54Y</b>		
PREPARED BY (PRINT COMPANY NAME): <b>Recovery Manager</b>		DATE PREPARED: <b>5/4/2005</b>		IS UNIT RIDEABLE: <input checked="" type="radio"/> YES <input type="radio"/> NO      (IF NOT EXPLAIN IN REMARKS BELOW)			
MILEAGE <b>77777777</b>		IGNITION KEY: <input type="radio"/> YES <input checked="" type="radio"/> NO		COLOR: <b>WHITE</b>		GENERAL CONDITION: <input checked="" type="radio"/> GOOD <input type="radio"/> AVERAGE <input type="radio"/> POOR <input type="radio"/> JUNK	
ACCESSORIES		<input type="checkbox"/> FWD CONTROLS <input type="checkbox"/> FAIRING		<input checked="" type="checkbox"/> FM RADIO <input type="checkbox"/> CRUISE CONTROL		<input checked="" type="checkbox"/> OTHER	
<input type="checkbox"/> AUTO TRANS <input type="checkbox"/> CUSTOM PIPES		<input checked="" type="checkbox"/> AM/FM/CD		<input checked="" type="checkbox"/> AM/FM/TAPE		<input type="checkbox"/> SADDLE BAGS <input checked="" type="checkbox"/> CUSTOM WHEELS	
MECHANICAL <input checked="" type="radio"/> GOOD <input type="radio"/> AVERAGE <input type="radio"/> POOR		GLASS/WINDSHIELD <input checked="" type="radio"/> GOOD <input type="radio"/> SCRATCHED <input type="radio"/> BROKEN(Explain)		TIRES    G - GOOD    A - AVERAGE    B - BALD    N - NONE  FRONT <b>G</b> REAR <b>A</b>		SEATS: <input type="radio"/> GOOD <input checked="" type="radio"/> AVERAGE <input type="radio"/> POOR    (Explain Below)	
LIST ADDITIONAL PROBLEMS AND / OR EXPLANATIONS IN THE COMMENT SECTION BELOW							
BODY: G - GOOD    A - AVERAGE    P - POOR    D - DENTED    R - RUST				ARE DENTS FROM COLLISION DAMAGE?			
OVERALL CONDITION: BODY <u>  A  </u> PAINT <u>  A  </u>				<input checked="" type="radio"/> YES <input type="radio"/> NO			
PLACE A "D" (DENTED) OR "R" (RUSTED), IF APPROPRIATE, ON THE PROPER LOCATIONS OF THE VEHICLES PICTURED BELOW:							
							
REMARKS / MISSING EQUIPMENT:							
VEHICLES RECOVERED FROM: <input type="radio"/> CUSTOMER <input checked="" type="radio"/> OTHER (SPECIFY) _____				ADDRESS RECOVERED FROM: <b>463 N Yonge St, Ormond Beach, FL 32174</b>			
WAS RELEASE SIGNED BY CUSTOMER? <input checked="" type="radio"/> YES <input type="radio"/> NO				IF NO, EXPLAIN			
PERSONAL PROPERTY <input checked="" type="radio"/> YES <input type="radio"/> NO				HAVE THE AUCTION SIGN BELOW INDICATING KEYS WERE RECEIVED WHEN THE VEHICLE WAS TURNED OVER TO THEM.  _____ AUCTION SIGNATURE                      _____ PRINT NAME			
ADDRESS WHERE CAR IS BEING STORED (REQUIRED): <b>1514 Granada Ave, Holly Hill, FL 32174</b>				COMPLETED BY: <b>Repossessed - Pending</b>			